

1402035304 - 110-203

Form 10-300  
(Dec. 1968)UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICENATIONAL REGISTER OF HISTORIC PLACES  
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE:	
COUNTY:	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

MD. HISTORICAL TRUST  
BOX 1704  
ANNAPOLIS, MD. 21404

1. NAME	
COMMON:	Emerson Pickett House
AND/OR HISTORIC:	

2. LOCATION			
STREET AND NUMBER: South side of Old National Pike (Frederick Road, MD 144)			
CITY OR TOWN: Lisbon			
STATE: Maryland	CODE:	COUNTY: Howard	CODE:

3. CLASSIFICATION			
CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> Building <input checked="" type="checkbox"/> Public <input type="checkbox"/>	Public Acquisition: <input type="checkbox"/>	Occupied <input checked="" type="checkbox"/>	Yes: <input checked="" type="checkbox"/>
Site <input type="checkbox"/> Structure <input checked="" type="checkbox"/> Private <input type="checkbox"/>	In Process <input type="checkbox"/>	Unoccupied <input type="checkbox"/>	Restricted <input type="checkbox"/>
Object <input type="checkbox"/>	Both <input type="checkbox"/>	Being Considered <input type="checkbox"/>	Unrestricted <input type="checkbox"/>
		Preservation work in progress <input type="checkbox"/>	No: <input type="checkbox"/>
PRESENT USE (Check One or More as Appropriate)			
Agricultural <input type="checkbox"/>	Government <input type="checkbox"/>	Park <input type="checkbox"/>	Transportation <input type="checkbox"/>
Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	Private Residence <input checked="" type="checkbox"/>	Other (Specify) <input type="checkbox"/>
Educational <input type="checkbox"/>	Military <input type="checkbox"/>	Religious <input type="checkbox"/>	
Entertainment <input type="checkbox"/>	Museum <input type="checkbox"/>	Scientific <input type="checkbox"/>	

4. OWNER OF PROPERTY			
OWNERS NAME: Emerson & Agnes Pickett			
STREET AND NUMBER: Old National Pike			
CITY OR TOWN: Lisbon	STATE: Md.	CODE:	

5. LOCATION OF LEGAL DESCRIPTION			
COURTHOUSE, REGISTRY OF DEEDS, ETC: CLERK OF THE CIRCUIT COURT			
STREET AND NUMBER: HOWARD COUNTY COURTHOUSE 40 S. MAIN			
CITY OR TOWN: SILICOTT Ct,	STATE: MARYLAND	CODE:	
APPROXIMATE ACREAGE OF NOMINATED PROPERTY:			

6. REPRESENTATION IN EXISTING SURVEYS			
TITLE OF SURVEY:			
DATE OF SURVEY: Federal <input type="checkbox"/> State <input type="checkbox"/> County <input type="checkbox"/> Local <input type="checkbox"/>			
DEPOSITORY FOR SURVEY RECORDS:			
STREET AND NUMBER:			
CITY OR TOWN:	STATE:	CODE:	

SEE INSTRUCTIONS

STATE:

COUNTY:

ENTRY NUMBER

DATE

FOR NPS USE ONLY

## 8. SIGNIFICANCE

## PERIOD (Check One or More as Appropriate)

Pre-Columbian ☐16th Century ☐18th Century ☒20th Century ☐15th Century ☐17th Century ☐19th Century ☐

## SPECIFIC DATE(S) (If Applicable and Known)

## AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

Aboriginal ☐Education ☐Political ☐Urban Planning ☐Prehistoric ☐Engineering ☐

Religion/Phi-

Other (Specify) ☐Historic ☐Industry ☐lasaphy ☐Agriculture ☐Invention ☐Science ☐Art ☐Landscape ☐Sculpture ☐Commerce ☐Architecture ☐

Social/Human-

Communications ☐Literature ☐itarian ☐Conservation ☐Military ☐Theater ☐Music ☐Transportation ☐

## STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

In 1973 The new owners, the Picketts, want to restore this but are reconsidering the advisability of such an endeavor. Major structural work is necessary, and the interior is gutted.

chimney with tin flue replacing the top 12'-20' of the stack.

If bearing log walls have been allowed to deteriorate this may be a hopeless restoration job.

SEE INSTRUCTIONS

HO-203

Emerson Pickett Log House, site  
Frederick Road (MD 144), Lisbon  
continued

## 7.1 Description

Exceptionally large for a log house, this building, almost square, covered with clapboard, has lost a large section of its foundations at the rear and is in imminent danger of collapse. The house faces north onto Frederick Road. Four bays by two, 2 1/2 stories high, a large cross-gable style peaked dormer with sawtooth decoration at the cornices has been added to the north slope of the roof. Exterior chimneys raise to the peak at each end of the house from heating fireplaces. The first floor front elevation contains two doors and two sets of 6/6 sash windows. At the second floor level are four windows containing sash of 2/2 panes. The full-length shed-roofed porch has square posts with Victorian brackets at the eaves.

Numerous alterations include removal of partitions to the interior, erosion of the cellar walls, exterior and interior, and changes in some windows from 6/6 to 2/2 lights, as well as a partly removed chimney with a tin flue replacing the top 12'-20' of the stack.

If bearing log walls have been allowed to deteriorate this may be a hopeless restoration job.

This house has been demolished. (JKC, 1998)

## 8.1 Significance continued

In 1973 the new owners, the Picketts, want to restore this house, but are reconsidering the advisability of such an endeavor. Major structural work is necessary, and the interior is gutted.

HO 203

Form 10-300  
(Dec. 1968)

UNITED STATES DEPARTMENT OF THE INTERIOR  
NATIONAL PARK SERVICE

N. R. FIELD SHEET

MD. HISTORICAL TRUST  
BOX 1704  
ANNAPOLIS, MD. 21404

NATIONAL REGISTER OF HISTORIC PLACES  
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE: MD.	
COUNTY: Howard	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

<b>1. NAME</b>	
COMMON: Emerson Pickett Log House	
AND/OR HISTORIC: 	

<b>2. LOCATION</b>			
STREET AND NUMBER: Frederick Road (MD 144)			
CITY OR TOWN: Lisbon			
STATE MD	CODE	COUNTY: Howard	CODE

<b>3. CLASSIFICATION</b>				
CATEGORY (Check One)	OWNERSHIP		STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> Building <input checked="" type="checkbox"/> Site <input type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>	Public <input type="checkbox"/> Private <input checked="" type="checkbox"/> Both <input type="checkbox"/>	Public Acquisition: In Process <input type="checkbox"/> Being Considered <input type="checkbox"/>	Occupied <input type="checkbox"/> Unoccupied <input type="checkbox"/> Preservation work in progress <input type="checkbox"/>	Yes: <input type="checkbox"/> Restricted <input type="checkbox"/> Unrestricted <input type="checkbox"/> No: <input checked="" type="checkbox"/>
PRESENT USE (Check One or More as Appropriate)				
Agricultural <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Entertainment <input type="checkbox"/>	Government <input type="checkbox"/> Industrial <input type="checkbox"/> Military <input type="checkbox"/> Museum <input type="checkbox"/>	Park <input type="checkbox"/> Private Residence <input checked="" type="checkbox"/> Religious <input type="checkbox"/> Scientific <input type="checkbox"/>	Transportation <input type="checkbox"/> Other (Specify) <input type="checkbox"/>	Comments <input type="checkbox"/>

<b>4. OWNER OF PROPERTY</b>			
OWNERS NAME: 			
STREET AND NUMBER: 			
CITY OR TOWN: Lisbon	STATE: Md.	CODE	

<b>5. LOCATION OF LEGAL DESCRIPTION</b>			
COURTHOUSE, REGISTRY OF DEEDS, ETC: Howard Co			
STREET AND NUMBER: 			
CITY OR TOWN: Bellicott City	STATE: Md.	CODE	

<b>6. REPRESENTATION IN EXISTING SURVEYS</b>			
TITLE OF SURVEY: 			
DATE OF SURVEY: 			
DEPOSITORY FOR SURVEY RECORDS: 			
STREET AND NUMBER: 			
CITY OR TOWN: 	STATE: 	CODE	

STATE:  
COUNTY:  
ENTRY NUMBER  
DATE

FOR NPS USE ONLY

ACREAGE

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

## 7. DESCRIPTION

CONDITION	(Check One)					
	Excellent <input type="checkbox"/>	Good <input type="checkbox"/>	Fair <input checked="" type="checkbox"/>	Deteriorated <input type="checkbox"/>	Ruins <input type="checkbox"/>	Unexposed <input type="checkbox"/>
INTEGRITY	(Check One)			(Check One)		
	Altered <input type="checkbox"/>	Unaltered <input checked="" type="checkbox"/>		Moved <input type="checkbox"/>	Original Site <input checked="" type="checkbox"/>	

DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE

HO 203 is a ~~log~~ <sup>log up claphouse</sup> frame dwelling of two story height with the facade at the N. elevation. The A frame roof has a centered cross gable with a wood sawtooth decoration at the corners.

The dwelling is four bays in length possessing two windows of 6/6 pane sash and two slightly recessed doors. At the 2nd floor level are four windows containing sash of 2/2 panes. The full length shed roofed porch has square posts with Victorian brackets at the eaves.

At both the E. and W. ends are single exterior ~~chimneys~~ <sup>stacks</sup> flush to the gable wall. Each has a single water shelf on their S. wall. The stack of the W. chimney has been removed (or fell) and has been replaced by a tin stove chimney.

## 8. SIGNIFICANCE

## PERIOD (Check One or More as Appropriate)

Pre-Columbian ☐16th Century ☐18th Century ☐20th Century ☐15th Century ☐17th Century ☐19th Century ☒

## SPECIFIC DATE(S) (If Applicable and Known)

## AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

Aboriginal ☐Education ☐Political ☐Urban Planning ☐Prehistoric ☐Engineering ☐

Religion/Phi-

Other (Specify) ☐Historic ☐Industry ☐losophy ☐Agriculture ☐Invention ☐Science ☐Art ☐Landscape ☐Sculpture ☐Commerce ☐Architecture ☐

Social/Human-

Communications ☐Literature ☐itarian ☐Conservation ☐Military ☐Theater ☐Architecture ☐Music ☐Transportation ☐

## STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

## 9. MAJOR BIBLIOGRAPHICAL REFERENCES

## 10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	0 ' "	0 ' "		0 ' "	0 ' "	
NE	0 ' "	0 ' "				
SE	0 ' "	0 ' "				
SW	0 ' "	0 ' "				

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	COOE	COUNTY	COOE
STATE:	COOE	COUNTY:	COOE
STATE:	COOE	COUNTY:	COOE
STATE:	COOE	COUNTY:	COOE

## 11. FORM PREPARED BY

NAME AND TITLE: <i>Riviera</i>		
ORGANIZATION: <i>MHT</i>	DATE: <i>3/71</i>	
STREET AND NUMBER:		
CITY OR TOWN:	STATE	COOE

## 12. STATE LIAISON OFFICER CERTIFICATION

## NATIONAL REGISTER VERIFICATION

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National ☐ State ☐ Local ☐

Name \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

I hereby certify that this property is included in the National Register.

\_\_\_\_\_  
Chief, Office of Archeology and Historic Preservation


Date \_\_\_\_\_

ATTEST:

\_\_\_\_\_  
Keeper of The National Register

Date \_\_\_\_\_




1. STATE COUNTY TOWN STREET NO.  ORIGINAL OWNER ORIGINAL USE PRESENT OWNER PRESENT USE WALL CONSTRUCTION NO. OF STORIES		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY	
		2. NAME  DATE OR PERIOD STYLE ARCHITECT BUILDER	
		3. FOR LIBRARY OF CONGRESS USE	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION		OPEN TO PUBLIC	
<p>frame 2 stories -</p> <p>4 bays. w.o. w. d. - w. b/g. Drs. recessed</p> <p>1 wind 2nd floor 2/2</p> <p>Cross gable center - w. saw tooth ridge.</p> <p>Shed roofed porch. 4 squared posts. - vict. hgt.</p> <p>centered ext. chimney w/ stone base on</p> <p>E. end. - single shelf at rear. - flush.</p>			
5. PHYSICAL CONDITION OF STRUCTURE    Endangered    Interior    Exterior			
<div style="display: flex; justify-content: space-between;"> <div>  <p>6. LOCATION MAP (Plan Optional)</p> </div> <div> <p>7. PHOTOGRAPH</p> </div> </div>			
8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.		9. NAME, ADDRESS AND TITLE OF RECORDER   DATE OF RECORD	

MARYLAND HISTORICAL TRUST - HISTORIC SITES SURVEY

Village of Lisbon, Howard Co., Md.

H0-203



J. R. RIVOIRE - FIELD SURVEYOR - M. H. T. 3/1971



HO 203

Pickett's log house Lis ben 18E 11/72



H0203

Pickett's log house Lisbon JSS 11/72